


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-267	Smoke	9/2/2009	ADS/TM	S11MM1006MH	Dry	Yes	595.10



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-267	Smoke	9/2/2009	ADS/TM	S11MM1006MH	Dry	Yes	595.10

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11MM1008G1	S11MM1008MH	S11KK1043MH	177.969	10
S11MM1006G1	S11MM1006MH	S11MM1008MH	207.116	8
S09MM1012G1	S09MM1012MH	S11MM1006MH	210.011	8

Observations & Photos

Obs_ID S1028-267-OB01

Address 4746 Park Heights Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S09MM1012MH

Comments Smoke from cleanout in back yard. 4746 Park Heights Ave.



Picture \S1028-267-OB01-P01.jpg

Comments Back of house, 4746 Park Heights Ave.

Obs_ID S1028-267-OB02

Address 4738 Park Heights Ave

Status Private

Source Cleanout

Location Paved concrete

Nearest MH S11MM1006MH

Comments Smoke from cleanout in paved concrete behind house. 4738 Park Heights Ave.



Picture \S1028-267-OB02-P01.jpg

Comments Back of house, 4738 Park Heights Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-267	Smoke	9/2/2009	ADS/TM	S11MM1006MH	Dry	Yes	595.10

Obs_ID S1028-267-OB03

Address 4730 Park Heights Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1006MH

Comments Smoke from cleanout in back yard. 4730 Park Heights Ave.



Picture \S1028-267-OB03-P01.jpg

Comments Back of house, 4730 Park Heights Ave.

Obs_ID S1028-267-OB05

Address 4718 Park Heights Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1006MH

Comments Smoke from cleanout in back yard. 4718 Park Heights Ave.



Picture \S1028-267-OB05-P01.jpg

Comments Back yard, 4718 Park Heights Ave.

Obs_ID S1028-267-OB04

Address 4726 Park Heights Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1006MH

Comments Smoke from cleanout in back yard. 4726 Park Heights Ave.



Picture \S1028-267-OB04-P01.jpg

Comments Back of house, 4726 Park Heights Ave.

Obs_ID S1028-267-OB06

Address 4710 Park Heights Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1008MH

Comments Smoke from service lateral in back yard. 4710 Park Heights Ave.



Picture \S1028-267-OB06-P01.jpg

Comments Back of house, 4710 Park Heights Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-267	Smoke	9/2/2009	ADS/TM	S11MM1006MH	Dry	Yes	595.10

Obs_ID S1028-267-OB07

Address 4708 Park Heights Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1008MH

Comments Smoke from cleanout in back yard. 4708 Park Heights Ave.



Picture \S1028-267-OB07-P01.jpg

Comments Back of house, 4708 Park Heights Ave.

Obs_ID S1028-267-OB08

Address 4708 Park Heights Ave

Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1008MH

Comments Smoke from service lateral in back yard. 4708 Park Heights Ave.



Picture \S1028-267-OB08-P01.jpg

Comments Back of house, 4708 Park Heights Ave.

Obs_ID S1028-267-OB09

Address 4702 Park Heights Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1008MH

Comments Smoke from cleanout in back yard. 4702 Park Heights Ave.



Picture \S1028-267-OB09-P01.jpg

Comments Back of lot, 4702 Park Heights Ave.

